

BEAUMONT LEYS CUSTODY SUITE

	Works
--	--------------

ALL CELLS	Installation of CCTV system
	Masking and isolation costs for CCTV (capital funding)
	Toilet flush replacements
	Sealant to benches, windows and door frames
	Replace cell call system.
	Cell heating ventilation grilles
	Remove wall between cell bench and toilet to remove blind spot on CCTV monitoring.
	Replacement cell benches and cell bench tops with Corian to remove any potential ligature points.
	Additional sealant around ceiling lights in cells - potential ligature points at both ends of lights
	Life-signs Monitoring in 4 cells

CELLS 11	Replace existing stainless steel toilet with Corian
	Install Corian basin

CELL DOORS	Quotation from Cell Security already received. To be examined and costs added with Dan Cooper 05/10/09
	Strip doors back to steel and paint again to remove graffiti.

CELLS 12, 13, 14	Existing Detention Rooms have no natural light. Costs please to provide roof light or light tube in each Cell.
------------------	--

CORRIDORS	Redecorate cells and corridor areas (capital funding).
	Upgrade lighting through custody suite.
	Old PACE booth to be kitted out with shelving to provide storeroom.
	Detention Room porcelain toilet and basin to be replaced with Corian.

SAMPLES ROOMS	Intoximeter Room requires metal lockable ceiling and integral lighting.
	Anite/Livescan Room requires metal lockable ceiling and integral lighting.

SHOWERS	Replace drain covers (x2) as holes +2mm
	Replace shower fittings (x2)
	Replace light fittings (x2)
	Fit modesty panels (x2)

CUSTODY DESK	Alteration to existing exhibits store with detainee property lockers
	Replacement desk with Corian finish to standard of SW and CU.

DETAINEE KITCHEN	Upgrade to kitchen including extractor fan
------------------	--

STAFF REST ROOM	Create staff rest room facility within existing suite (already provided)
-----------------	--

	Key pass to Medical Room door (CJ funding)
--	--

MEDICAL ROOM	Discreet alarm (CJ funding)
	Plastic chairs (CJ funding)
	Elbow operated taps and wall mounted clinical waste bin (CJ funding)
	Metal lockable ceiling and integral lighting.
INTERVIEW ROOMS	Metal lockable ceiling and integral lighting to interview rooms (x4) and interview room corridors.
	Install digital cabling in preparation for digital interview recording.
	CCTV coverage in new interview room corridor.
CHUTE	New bench. Existing bench too narrow.
	Replace external and internal double doors with one large wide opening doors.
EXERCISE YARD	Replacement drain covers (CJ funding)
	Replacement lights (CJ funding)
	Replacement doors and handles (CJ funding)
	Raise roof grille to avoid potential ligature points.
	All mortar on walls in exercise yard, particularly around windows to be checked. Multiple small holes +2mm.

Green

Amber

Version 3: 12/12/09

Updated 12/12/09 by Superintendent S. Harrod, Criminal Justice